

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

We Protect Hoosiers and Our Environment.

Mitchell E. Daniels Jr. Governor

Thomas W. Easterly
Commissioner

Northwest Regional Office 8380 Louisiana Street Merrillville, Indiana 46410 (219) 757-0265 Toll Free (888) 209-8892 Fax (219) 757-0267 www.idem.IN.gov

Ms. Val Blumenfeld Brown Inc. 720 W. US Hwy 20 Michigan City, IN 46360 June 30, 2010

Re:

Inspection Summary

Yard 520 Landfill Permit # 64-04/64-07

Town of Pines, Porter County

Dear Ms. Blumenfeld:

On June 29, 2010, a representative of the Indiana Department of Environmental Management, Northwest Regional Office, conducted an inspection of Yard 520 Landfill, located at US Hwy 20 and St. Rd 520 in the Town of Pines, Indiana. This inspection was conducted pursuant to IC 13-14-2-2. For your information, and in accordance with IC 13-14-5, a summary of the inspection is provided below:

Type of Inspection:	<u>X</u>	Routine Complaint Other: Follow-up to corrective action plan
Results of Inspection:		No violations were observed Violations were observed but corrected during the inspection (See inspection report) Violations were observed (See inspection report) Additional information/review is required to evaluate overall compliance Violations were observed and will be referred to the Land Enforcement Section Other

Ms. Blumenfeld Page 2

Please contact me upon receipt of this letter to setup a full walk around inspection of the Yard 520 landfill. If you should have any questions or comments please contact me at 219-757-0276. Thank you for your attention to this matter.

Sincerely,

Ashley Snyder

Agricultural & Solid Waste Compliance Inspector Indiana Department of Environmental Management Northwest Regional Office

Enclosure

cc: Ms. Tamara Perkins, Weaver Boos Consultants

Mr. Tim Drexler, US EPA Region 5

Ms. Brenda Waters, Indiana Dunes National Parks Service Mr. Charles Morris, Indiana Dunes National Parks Service

Mr. Kevin Herron, Indiana Department of Environmental Management

Porter County Health Department

Porter County Solid Waste Management District



Facility Name

Yard 520 landfill

Photographer

Ashley Snyder

Date/Time


2:30 PM 6-29-10

Others Present

N/A

Description

West slope near the seep sampling site where work has been conducted to re-grade and reseed the slope.



Facility Name

Yard 520 landfill

Photographer

Ashley Snyder

Date/Time

2:30 PM 6-29-10

Others Present

N/A

Description

West slope near the seep sampling site where work has been conducted to re-grade and reseed the slope.



Facility Name

Yard 520 landfill

Photographer

Ashley Snyder

Date/Time


2:30 PM 6-29-10

Others Present

N/A

Description

West slope near the seep sampling site where work has been conducted to re-grade and reseed the slope.



Facility Name

Yard 520 landfill

Photographer

Ashley Snyder

Date/Time


2:30 PM 6-29-10

Others Present

N/A

Description

West slope near the seep sampling site where work has been conducted to re-grade and reseed the slope.



Facility Name

Yard 520 landfill

Photographer

Ashley Snyder

Date/Time

2:30 PM 6-29-10

Others Present

N/A

Description

Entrance near the West slope where no trespassing signage has been affixed and gates have been locked as access control.



AGRICULTURAL AND SOLID WASTE COMPLIANCE

State Form 47272 (R3/12-08) INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

File:	County:		7	Type of Report:							
	Porter Porter			Routine	e 🔲 Con	ıplaint 🛛 Fo	ollow-Up	☐ Spill			
Name of Inspector:			Date	of Inspecti	on:		Time	In:	Time Out:		
Ashley Snyder	<u>/der</u> <u>6/29/2010</u>				2:00	<u>PM</u>	<u>2:30 PM</u>				
Name of Facility:								Permit:			
Yard 520 RWS II/III Landfill						64-04/64-07					
Address/Location (number and street, city, state, and zip):											
US- HWY 20 and St RD 520 Town of Pines, Indiana											
Facility located by	GPS	Photograp	ohs	Samples	Samples			Pollution prevention opportunities			
Yes No		✓ Yes	☐ No	Yes Yes	⊠ No	Yes	⊠ No	☐ Yes 🔯	No		

Comments: This inspection was conducted as a follow-up to the letter dated February 25, 2010 from Ms. Tamara Perkins, Weaver Boos Consultants, in which a plan was outlined to bring the site back into compliance with the violations cited in the December 12, 2009 inspection. The corrective action plan indicated that all required work would be completed on or before June 28, 2009. This inspector drove out to the site to observe the completed work. Once at the site it was noted that no one was onsite nor was any work currently being conducted. The West slope was observed as having been re-graded and reseeded and straw has been placed on top of the surface to stabilize the area until the vegetation can do so. The West gate was also observed and the no trespassing signs were in place.

This inspector only drove the perimeter of the site and did not walk the fill area. A full inspection of the landfill will need to be setup with Ms. Blumenfeld in order to walk the fill and observe all completed work, and discuss access control. At that time compliance will be assessed. Currently additional information is needed to evaluate overall compliance.

VFC Information
Program: Confined Feeding, SW Landfill, SW Processing
Document Date:

SW Program ID #:

CFO/CAFO #:

6/30/10

Signature of person receiving oral/written report (Inspection conducted in accordance with IC 13-14-5)	Date (month, day, year)
To be mailed with summary letter	<u>6/29/2010</u>
Certificate of Compliance left with operator (Check only if violations are noted above).	
☐ Yes ☐ No	

VFC Information
Program: Confined Feeding, SW Landfill, SW Processing
Document Date: SW Program ID #: CFO/CAFO #:_____